



## State of Vermont

Department of Fish and Wildlife  
Department of Forests, Parks and Recreation  
Department of Environmental Conservation  
State Geologist  
RELAY SERVICE FOR THE HEARING IMPAIRED  
1-800-253-0191 TDD>Voice  
1-800-253-0195 Voice>TDD

AGENCY OF NATURAL RESOURCES  
Department of Environmental Conservation  
Waste Management Division  
103 South Main Street/West Office  
Waterbury, Vermont 05671-0404  
(802) 241-3888  
FAX (802) 241-3296

July 19, 2001

Mr. Peter Murphy  
Murphy Realty  
20 Hastings Street  
St. Johnsbury, Vermont 05819

RE: Petroleum Contamination at the Yankee Traveler Motel, St. Johnsbury, Vermont ( SMS Site # 2001-2883)

Dear Mr. Murphy:

The Sites Management Section (SMS) has received the Underground Storage Tank (UST) closure report which outlines the subsurface conditions for the above referenced site. The fieldwork was conducted by Griffin International, Inc., on May 21, 2001. The report is dated May 30, 2001 and summarizes the degree and extent of contamination encountered. The UST removed include:

- UST #1 - 1,000 gallon No. 2 fuel oil UST

During the site activities, screened soils had concentrations up to 194 parts per million (ppm) as measured by a photoionization detector (PID). The peak PID reading was measured at a depth of approximately 6.5 feet below ground surface (fbs) in the UST excavation. Numerous holes evident in the tank. All soil was used as backfill at the conclusion of the UST program. The limits of soil contamination were not defined.

The site soils consisted medium- coarse brown sands and gravel. No soil samples were collect for laboratory analysis. No groundwater or free phase product was encountered in the excavation. Bedrock was not encountered at a depth of 7.0 feet in the excavation.

The Yankee Traveler Motel was inspected for sensitive receptors. The possible receptors potentially affected include the site soils, groundwater and the on-site building. Additional potential receptors include municipal water and sewer lines.

Based on the report information, the SMS has determined additional work is necessary to determine the severity of the contamination. Due to possible contamination to nearby receptors, the SMS requests that the Yankee Traveler Motel retain the services of a qualified environmental consultant to perform the following:

- ☐ Further define the degree and extent of the contamination to the soil.
- ☐ Determine the degree and extent of contamination, if any, to groundwater. A sufficient number of monitoring sites should be installed to adequately define the severity of site contamination. Analyze groundwater samples for BTEX and MTBE using EPA Method 8021B and Total Petroleum Hydrocarbons (TPH) using EPA Method 8015. At sites proximal to water supply sources, determine the hydrologic relationship of the contaminated area to the water supply source. Pumping influences should be considered in the evaluation.
- ☐ If appropriate, determine if the airspace beneath the site and site adjacent building(s) (e.g. basements) has been impacted by the release using a PID. Wall and floor construction and susceptibility to vapor migration should be noted. PID measurements should be made in cracks and/or joints likely impacted. If

the airspace has been impacted, SMS requests confirmatory sampling and laboratory analyses be performed using EPA Method TO-2.

- ☐ Assess the potential for contaminant impact on sensitive receptors. Base this update on all available information and include basements of adjacent buildings, nearby surface water, any proximal drinking water sources, wetlands, sensitive ecologic areas, outdoor or indoor air, sewers, or utility corridors. Sample and analyze any at-risk water supplies for BTEX, TPH and MTBE compounds.
- ☐ Determine the need for long-term treatment and/or monitoring that addresses groundwater contamination.
- ☐ Submit a summary report that outlines the work performed, as well as provides conclusions and recommendations. **As appropriate** include analytical data; a site map showing the location of any potential sensitive receptors, stockpiled soils and monitoring or sample locations; an area map; detailed well logs; and a groundwater contour map.
- ☐ With the Workplan or Expressway form, please submit a site location map at an approximate scale of 1:24000 showing the location of the site. Please include a scale, a north arrow, the SMS site number, and a citation of the source map. The purpose of this map is to enable the SMS to enter the site location into a Geographical Information Systems database.


Please have your consultant submit a preliminary work plan and cost estimate within fifteen days of your receipt of this letter, so it may be approved prior to the initiation of onsite work. Enclosed please find a list of consultants who perform this type of work as well as the brochure "*Selecting Your UST Cleanup Contractor*," which will help you in choosing an environmental consultant.

Based on current information, the underground storage tank at the Yankee Traveler Motel is eligible for participation in the Petroleum Cleanup Fund (PCF). You must provide written proof to the SMS that you hold no other applicable insurance in order to receive reimbursement from the PCF. The owner or permittee must pay for the removal and/or repair of the failed tank(s), and for the initial \$250.00 of the cleanup. The fund will reimburse the tank owner or permittee for additional eligible cleanup costs of up to \$1 million. All expenditures must be pre-approved by the Agency or performed in accordance with the "*Site Investigation Guidance*" expressway program. Please refer to the enclosed guidance document titled, "*Procedures for Reimbursement from the Petroleum Cleanup Fund*" for additional information concerning the PCF.

The Secretary of the Agency of Natural Resources reserves the right to seek cost recovery of fund monies spent at the Yankee Traveler Motel, if the Secretary concludes that the Yankee Traveler Motel is in significant violation of the Vermont Underground Storage Tank Regulations or the Underground Storage Tank statute (10 V.S.A., Chapter 59).

We are here to help make this process as effective and uncomplicated as possible. Please call me with any questions you may have. I can be reached at (802) 241-3876.

Sincerely,

  
Chuck Schwer, Supervisor  
Sites Management Section

Enclosures(3)

cc: St. Johnsbury Select Board w/o enclosure  
St. Johnsbury Health Officer w/o enclosure  
DEC Regional Office w/o enclosure  
Don Tourangeau, Griffin International, Inc.